Stryker Stretcher Bumper Strip Replacement (Pair) – 1010-700-45



Stock Photo – Options May Vary

FACTORY NEW

Stryker Stretcher Bumper Strip Replacement (Pair) – 1010-700-45. Do your Stryker stretcher bumper strips look old, nicked, and scraped? This replacement set brings them back to life.

Furthermore, it comes in grey and is sold as a cut-to-fit pair for a wide range of Stryker models. Just measure your current strips, cut the new ones to match, and snap them into place. In addition, this is one of the easiest, most affordable ways to freshen up the look of your Stryker stretcher.

Moreover, no tools or special skills are needed.

FEATURES

- Snap-in installation, no tools required
- Refreshes the look of worn, nicked, or scraped bumpers
- Fits a wide range of Stryker stretcher models
- Free shipping
- Stryker 1001, 1009, 1501, 1509

SPECIFICATIONS

- Color: Grey
- Length: 8 ft. x 2 (1 pair of strips)
- Cut-to-fit design
- Made in USA

**Brochure and images are a general overview of the product. Actual product options may vary.*

Toll-Free 800-627-3215 | Local 813-740-8640
salesteam@venturemedical.com

© 2007-2026 Venture Medical ReQuip, Inc.

View this product online →