

Stryker Big Wheel Dampener | 1040-006-209



Stock Photo - Options May Vary

FACTORY NEW

Replacement Stryker Big Wheel Dampener | 1040-006-209 is a non-OEM gas spring for the big wheel on Stryker Prime 1115 and M-Series 1015 stretchers. Does your big wheel slam when you release the brakes, or does the brake pedal feel hard to push? A worn-out gas dampener is a common cause.

As the gas pressure drops, the spring snaps back or binds. In addition, this direct-replacement dampener restores smooth, controlled movement to the big wheel assembly. It cushions each transition, so the linkages are protected from shock damage.

As a result, caregivers get the smooth pedal feel they expect.

FEATURES

- Direct replacement for OEM# 1040-006-209
- Restores smooth, controlled big wheel movement
- Stops the big wheel from slamming when brakes release
- Eases a hard-to-push brake pedal
- Cushions mechanical transitions

SPECIFICATIONS

- Part Number: 1040-006-209
- OEM Number: 1040-006-209
- Type: Big wheel dampener (gas spring), non-OEM direct replacement
- Fits: Stryker Prime 1115 and M-Series 1015 stretchers
- Overall Extended: 165 mm

**Brochure and images are a general overview of the product. Actual product options may vary.*

Toll-Free 800-627-3215 | Local 813-740-8640

salesteam@venturemedical.com

[View this product online →](#)