Stryker 1061 Foot Bumper | 1061-40-18



Stock Photo – Options May Vary

FACTORY NEW

Stryker 1061 Replacement Foot End Bumper, PN: 1061-40-18 – New. This non-OEM foot bumper is a direct replacement for Stryker 1061 stretchers.

In addition, it restores the look and protection of your stretcher's foot end without the cost of a whole new unit. Foot bumpers wear down over time from daily use and repeated contact during patient transport.

As a result, a worn or cracked bumper can leave your stretcher looking rough and reduce foot-end protection. This bumper is built as a direct fit, so installation is quick, with no need to modify your existing frame or hardware.

FEATURES

- Direct OEM Replacement
- Replaces P/N 1061-40-18
- Durable Material
- Color: Purple

SPECIFICATIONS

- MPN: 1061-40-18
- Condition: New
- Type: Non-OEM replacement
- Compatible with: Stryker 1061 Gynnie stretcher
- Application: Foot end section bumper

**Brochure and images are a general overview of the product. Actual product options may vary.*

Toll-Free 800-627-3215 | Local 813-740-8640
salesteam@venturemedical.com

© 2007-2026 Venture Medical ReQuip, Inc.

View this product online →