Stryker End Cap (Pair) | PN: 100-30-29



Stock Photo – Options May Vary

FACTORY NEW

Stryker Stretcher End Cap Part, PN: 1001-30-29. This end cap plug is a direct replacement for your Stryker stretcher. You'll receive one pair of end caps (qty 2).

In addition, it fits models such as the Stryker 1001 and Stryker 1501. Over time, end caps can crack, loosen, or go missing from daily use and repeated handling. As a result, a damaged or missing end cap can leave exposed hardware on your stretcher frame, affecting both appearance and safety.

Replacing it restores your stretcher to a clean, finished look while protecting the frame underneath.

FEATURES

- Direct OEM Replacement
- P/N 100-30-29
- Durable Material
- Color: Black

SPECIFICATIONS

- MPN: 1001-30-29
- Quantity: 1 pair (2 end caps)
- Compatible with: Stryker 1001, Stryker 1501
- Application: Stretcher frame end cap/plug

**Brochure and images are a general overview of the product. Actual product options may vary.*

Toll-Free 800-627-3215 | Local 813-740-8640
salesteam@venturemedical.com

© 2007-2026 Venture Medical ReQuip, Inc.

View this product online →