Stryker 5050 Stretcher Chair Replacement Pad



Stock Photo – Options May Vary

FACTORY NEW

Replacement Pad for Stryker 5050 Stretcher Chair: VMR-SP-5050. This high-quality, two-piece pad is specifically designed for the Stryker 5050 Stretcher Chair, offering 2 inches or 3 inches of pad thickness, comfortable padding to ensure optimal patient support and comfort during transport or procedures.

The two-piece design allows for easy installation and maintenance, making it a convenient choice for healthcare providers. Note: Pad shown in use on Stretcher.

Stretcher not included, sold separately.

**Brochure and images are a general overview of the product. Actual product options may vary.*

© 2007-2026 Venture Medical ReQuip, Inc.

View this product online →

Toll-Free 800-627-3215 | Local 813-740-8640

salesteam@venturemedical.com