

GE MAC 5000/5500 Gas Spring Shock | P/N 416015-001



Stock Photo - Options May Vary

FACTORY NEW

The GE MAC 5000/5500 Gas Spring is a brand-new non-OEM replacement for the printer door gas strut, designed for dependable operation in EKG units. This gas spring damper assists in smoothly opening the printer door and securely holding it in position, providing safe and convenient access during routine use and maintenance.

This replacement gas spring fits both GE MAC 5000 and GE MAC 5500 EKG units. Gas springs commonly fail over time, and this part restores proper door support and improves daily workflow efficiency while replacing P/N 416015-001 for reliable compatibility.

Installation is quick and straightforward. Reuse the current threaded end fittings from the existing OEM gas spring by removing the threaded ends and attaching them to the new gas spring for a secure fit, avoiding extra hardware costs and reducing downtime.

FEATURES

- Brand New
- Non OEM
- Replaces P/N 416015-001

**Brochure and images are a general overview of the product. Actual product options may vary.*

Toll-Free 800-627-3215 | Local 813-740-8640

salesteam@venturemedical.com

[View this product online →](#)