

Replacement Stretcher Pad for Stryker 5050 Stretcher Chair



Stock Photo - Options May Vary

FACTORY NEW

Replacement pad designed specifically for the Stryker 5050 Stretcher Chair. Features a two-piece construction with 2 inches of thick padding to provide optimal patient support and comfort during transport or medical procedures.

The two-piece design enables straightforward installation and maintenance, reducing downtime and simplifying pad replacement. This makes it an efficient choice for healthcare facilities managing multiple stretcher chairs.

Available in black. Pad only; stretcher chair sold separately.

**Brochure and images are a general overview of the product. Actual product options may vary.*

Toll-Free 800-627-3215 | Local 813-740-8640

salesteam@venturemedical.com

[View this product online →](#)