



www.venturemedical.com

Venture Medical ReQuip, Inc.  
 6008 Bonacker Drive  
 Tampa, FL 33610  
 800-627-3215 | 813-740-8640  
 Fax: 800-466-1251  
 sales@venturemedical.com

## Stretcher Replacement Pad Options & Accessories – New



MFG	Model	P/N	Details
Hill-Rom	Transtar P-8000 – 24” Width	VM-HRP8000-PS24	4" Thickness
Hill-Rom	Transtar P-8000 – 27” Width	VM-HRP8000-PS27	4” Thickness
Hill-Rom	P-8050	VM-HRP8050-PS	4" Thickness
Stryker	Renaissance / Advantage Series 24” Width	VM-STRRA-PS24	4" Thickness
Stryker	Renaissance / Advantage Series 27” Width	VM-STRRA-PS27	4” Thickness
Stryker	5050	VM-STR5050-PS	3 " Thickness
Stryker	1061	VM-STR1061-PS	4 " Thickness
Stryker	1068	VM-STR1068-PS	3 " Thickness
Stryker	1069	VM-STR1069-PS	3 " Thickness
Wy'East	Totalift II	VM-WYETL2-PS	2 " Thickness

### Most Common Accessories

Universal IV Pole Stainless Steel, Non-Adjustable, Economy	VMR-1V1
Stretcher Patient Strap – Sold Each	PR-9000

**\*\*Please contact us for a full list of specialty accessories available.**

**VENTUREMEDICAL.COM**

© 2007-2025 Venture Medical ReQuip, Inc.