

WyEast Totalift II Stretcher Chair Replacement Pad



Stock Photo - Options May Vary

FACTORY NEW

WyEast Totalift II Stretcher Chair Replacement Pad. This pad is built specifically for the WyEast Totalift II, so it restores comfort and support without the cost of replacing the whole chair.

The one piece design has no seams or gaps for fluids to collect in, so cleaning stays simple. At 2.5 inches thick, the pad gives patients solid cushioning during transport and extended stays in the chair.

The 23 inch width matches the WyEast Totalift II frame. This helps the pad sit securely and hold its shape under regular use.

FEATURES

- Fits End Bumper Pads for Hausted Pediatric Crib model number: 4160
- Pad thickness: 3 inches
- Set of two End Bumper Pads
- Upholstery Color: Black

SPECIFICATIONS

- Width: 23"
- Thickness: 2.5"
- Pieces: 1
- Color: Black

**Brochure and images are a general overview of the product. Actual product options may vary.*

Toll-Free Local
800-627-3215 | 813-740-8640

salesteam@venturemedical.com

[View this product online →](#)