

Replacement Stretcher Pad for Stryker 1079 Stretcher



Stock Photo - Options May Vary

FACTORY NEW

Replacement pad for Stryker 1079 stretchers designed to provide lasting comfort and durability in patient care environments. The 4-inch thick pad is constructed from 100% polyurethane foam and features a 4-way stretch cover that enhances flexibility and fit. Welded seams add strength, while the breathable zipper design allows the foam to recover faster after use.

The pad resists bacteria, stains, and tears, maintaining a clean and professional appearance. A non-skid black bottom keeps the pad securely in place during patient transport and movement. The durable construction withstands repeated cleaning and daily hospital use.

Dimensions are 76 inches in length and 24 inches in width, with 11-inch head beveled corners and square bottom corners for precise fit on Stryker 1079 stretchers. The pad meets California Technical Bulletin CAL117 and CTB117 flammability standards.

**Brochure and images are a general overview of the product. Actual product options may vary.*

Toll-Free 800-627-3215 | Local 813-740-8640

salesteam@venturemedical.com

[View this product online →](#)