

Stryker Stretcher Backrest Gas Spring | 1010-31-78 - New



Stock Photo - Options May Vary

FACTORY NEW

Stryker Stretcher Backrest Gas Spring: 240N. Restore smooth backrest positioning with this Stryker stretcher backrest gas spring, part number 1010-31-78. Moreover, this brand-new non-OEM replacement ensures dependable daily performance. If your stretcher uses two backrest gas springs, this strut likely matches your application. As a direct replacement, it installs quickly and minimizes equipment downtime.

Additionally, this gas spring fits numerous Stryker stretcher models. Compatible models include 0735, 0737, 0748, 721, 1001, 1009, 1501, and 1509. It also fits 1210, 1211, 1231, 1710, 1711, and 1731. Furthermore, it supports 1061, 1068, 1069, 1079, 1089, 1080, 1010, and 1510.

Therefore, medical facilities can confidently order replacements for multiple units. Constructed from durable materials, this stretcher gas spring withstands heavy clinical use. As a result, caregivers achieve controlled, smooth backrest movement during patient transport.

FEATURES

- Replaces Stryker P/N: 1010-31-78
- Used for fowler (backrest) adjustment
- 240N
- Brand New
- Non-OEM Replacement

**Brochure and images are a general overview of the product. Actual product options may vary.*

Toll-Free | Local
800-627-3215 | 813-740-8640

salesteam@venturemedical.com

[View this product online →](#)